


Clearmake Electropure™ Particle Removal Guide



For efficient treatment, water pH should be between 5.5 and 8.0.

< indicates process not complete in this range.

Disclaimer: This information has been prepared by Clearmake Pty Ltd to act as a general guide only. Results may vary based on input water quality, flow rates etc.

Lab testing of input water can be undertaken to determine site specific performance.